

# SAFETY BULLETIN

<b>Safety Bulletin No.</b>	<b>2023 03</b>	<b>Date Issued</b>	February 2023
<b>Subject</b>	<b>Changed Conditions – Airside Apron Road</b>		
<b>Area of Concern</b>	Darwin Airside		
<b>Issued By</b>	Mike Clancy - Airside Manager		

This **Safety Bulletin** is issued to advise all operators of changed conditions on the airside apron road due to works in progress Terminal Expansion and Bay 3 Apron and Aerobridge upgrades.

These works are on and adjacent to the active areas of the Air Transport Apron (ATA) and require temporary restrictions and permanent changes to the Airside Apron Road abeam the Baggage Make Up (BMU) area during the works.

Temporary changes can include temporary or intermittent airside road closure and diversions around work sites and an advice will be issued showing the changed route and traffic management plan as required.

As part of the Terminal Expansion Works between Bays 2 and 3 a scaffold has been erected over the airside road abeam the BMU with the following changed conditions and restrictions in place:

**Apron Airside Road** reduced to single lane adjacent the scaffold support structure – vehicles proceeding from west to east (lane closest to building) must **'GIVE WAY'** to oncoming vehicles.



**BMU Lateral No 2** restricted on left hand side (facing the road) – 2<sup>nd</sup> lane closed

**'NO LEFT TURN'** when **exiting the BMU.**



**Issued By: Mike Clancy**  
**Airside Manager**  
**Darwin International Airport**

**THINK SAFELY, ACT SAFELY**