

SAFETY BULLETIN

Safety Bulletin No.	2020 08	Date Issued	27 October 2020
Subject	Accessing DIA Terminal Roof		
Area of Concern	Low headroom doorways & excessive glare		
Issued By	<i>Steve Caldwell</i> (WHS – 0402 782 375)		

Introduction

Recently a contractor struck his head on a low headroom door frame whilst returning from outside to inside. It was a hot humid and glary day which exacerbated the problem. A subsequent investigation revealed that there was no hazard tape in place highlighting the low headroom nature of the door frame. This has since been rectified (photo refers).



Low headroom door frame

Action

Please be reminded that there are a number of low headroom access points when accessing the DIA terminal roof. Please be mindful of this and remind contractors of this particularly when returning from outside to inside due to likely glare, heat and humidity.

Please remember to wear anti-glare sunglasses when accessing the roof, particularly at this time of year.

Signed: *SteveC*

Health & Safety Manager

THINK SAFELY, ACT SAFELY